

Shaping and Forming

CHAPTER PREVIEW

This is the pottery chapter! Many of the techniques that are now being used to shape high-tech ceramics have been used by potters for millennia, but have been refined for today's high-tech applications and for new ceramic materials. We will try to relate shaping to the potter's craft throughout the chapter.

We can just process dry powder and sinter it, but it is much more common to add some amount of liquid, just as the potter adds water to clay; we then shape the object and fire it. Shaping transforms an unconsolidated powder mixture into a coherent, consolidated body having a chosen geometry. The selection of a shaping operation for a particular product is very dependent on the size and dimensional tolerances of the product, the requisite microstructural characteristics, the levels of reproducibility required, economic considerations, and of course the required shape. We cover shaping of glass in Chapters 21 and 26 so here we will consider the similarities in processing glass and crystalline ceramics. Similarly, we discuss thick films in Chapter 27; here we concentrate on three-dimensional (3D) objects varying from fish-hooks to turbine blades. However, we will cover slip casting, which we used only in a limited way for thin films.

23.1 THE WORDS

There is a special vocabulary for shaping ceramics because it is an ancient art. Once the constituent powders have been prepared in the desired purity and particle size most ceramic products must be fabricated into useful shapes. Many shaping methods are used for ceramic products and these can be grouped into three basic categories, which are not necessarily independent.

1. Powder compaction: dry pressing, hot pressing, cold isostatic pressing, etc.
2. Casting: using a mold with the ceramic as, or containing, a liquid or slurry
3. Plastic forming: extrusion, injection molding, etc.—using pressure to shape the green ceramic

Powder compaction is simply the pressing of a free-flowing powder. The powder may be dry pressed (i.e., without the addition of a binder) or pressed with the addition of a small amount of a suitable binder. The pressure is applied either uniaxially or isostatically. The choice of pressing method depends on the shape of the final product. We make simple shapes by applying the pressure uniaxially; more complex shapes require isostatic pressing.

Casting ceramics is carried out at room temperature and generally requires the ceramic powder particles to be suspended in a liquid to form a slurry; note this process

is quite unlike the casting of metals. The slurry is then poured into a porous mold that removes the liquid (it diffuses out through the mold) and leaves a particulate compact in the mold. This process is known as slip casting. The process has been used to form many traditional ceramic products (e.g., sanitary ware) and more recently has been used in forming advanced ceramic products (e.g., rotor blades for gas turbines). The other main casting process for ceramics is tape casting, which, as you would guess, is used to make thick films or sheets and is described in Chapter 27.

Plastic forming consists of mixing the ceramic powder with a large volume fraction of a liquid to produce a mass that is deformable (plastic) under pressure. Such processes were developed and used originally for clay and have since been adapted to polymeric materials. For traditional clay-based ceramics the liquid is mainly water. For ceramic systems that are not based on clay, an organic may be used in place of, or in addition to, water. The binders are often complex and contain multiple components to achieve the required viscosity and burn-out characteristics.

Table 23.1 lists the major methods that are included in each of the above categories and the types of shape that can be produced. First some of the words:

Binder is a component that is added to hold the powder together while we shape the body.

Slurry is a suspension of ceramic particles in a liquid.

TABLE 23.1 Various Shaping Methods for Ceramic Components

Shaping method	Type of feed material	Type of shape
Dry pressing	Free-flowing granules	Small and simple
Isostatic pressing	Fragile granules	Larger and more intricate
Extrusion	Plastic mass using a viscous polymer solution	Elongated with constant cross section
Injection molding	Organic binder giving fluidity when hot	Complex
Slip casting	Free-flowing cream	Mainly hollow

Plasticizer is the component of a binder that keeps it soft or pliable; it improves the rheological properties. *Green* is a ceramic before it is fired. Brown, white, or gray potter's clays are well known green ceramics. *Slip* is the liquid-like coating used to form the glaze when fired.

Some of the shaping methods we will describe in this chapter produce a ceramic compact that is strong enough to be handled and machined; however, it is not fully dense and the bonds between the grains are not strong. This is called the "green" state and represents a transition state between the loose powder and the high-density sintered product. Other shaping methods, those that involve the use of high temperatures and pressures, can directly produce a very dense sintered product. Much of what we talk about here has a parallel in the field of powder metallurgy; the theme is often *processing powders*, which are not necessarily ceramic powders (e.g., they could be pharmaceuticals).

23.2 BINDERS AND PLASTICIZERS

It is often necessary to add a binder to the ceramic powder. The binder has two functions. In some shaping methods, such as extrusion, the binder provides the plasticity necessary for forming. The binder also provides the dry (green) shape with strength sufficient to survive the handling process between shaping and sintering. One of the most important requirements for the binder is that we must be able to eliminate it from the compact during the firing process without any disruptive effect: polymers are thus often ideal binders.

In pottery, the binder is often water that is present in sufficient quantity to make the clay easily shaped with the shape being retained during firing. The idea is that we then add a plasticizer to optimize the rheology of the material. Note that these processes are not exclusive to ceramics but are general to powder processing. The distinction between binder and plasticizer is sometimes not too clear.

Binders can also be used when metal powders are processed; PMC is *precious-metal clay*.

23.3 SLIP AND SLURRY

The word slip appears to come (according to Webster's) from the Old English words meaning cream: the suspension of curds in the liquid when making cheese; the cheese was actually sieved through a "slippe clothe."

In general, slip consists of fine (<10µm) ceramic-powder particles that are suspended in a fluid. In the pottery industry, the liquid is usually water. The suspension can have a solid content up to ~60 vol%. Deflocculents are added to the slip to modify the electrical environment of each particle so that the particles repel each other.

Deflocculants: Since deflocculation is defined as the process by which flocules present in a liquid break up into fine particles producing a dispersion, a deflocculant is an additive that causes this process. In other words, deflocculation is the opposite of coagulation. (A flocule is a small piece of matter or a flock.)

Colloids: Colloids are defined very generally as any substance that consists of particles substantially larger than ordinary molecules but much too small to be visible without optical magnification (~1 nm to 10µm). They can be linked or bonded together in various ways. Colloidal systems can take several forms; the one relevant to us is the dispersion of one substance in another. Brownian motion has interested scientists for generations. Slip is a colloid. We can change the properties of the slip by adding flocculants or deflocculants.

Slurry: Clay particles are suspended in a liquid (water in the case of pottery). As the amount of water is decreased it becomes more solid. Glazes used in pottery have the same base as the clay but with more water content. Potter's clay is made by first producing a slip from naturally occur-

BINDERS

Poly (vinyl alcohol) (PVA) and poly (ethylene glycol) (PEG) are the two of the most popular binders for dry-pressing ceramics:

PVA provides a high green strength.
PEG provide a high green density.




FIGURE 23.1 The stages in dry pressing.

ring clays. The slip is repeatedly filtered to produce a consistency that is constant over long periods of manufacture. Slabs of clay are then formed from this colloid by allowing most of the water to evaporate. The final product may be shaped by extrusion and packaged to prevent further loss of water.

23.4 DRY PRESSING

Dry pressing is ideally suited to the formation of simple solid shapes and consists of three basic steps: filling the die, compacting the contents, and ejecting the pressed solid.

Figure 23.1 shows a schematic diagram of the double-action dry-pressing process. In a double-action press both the top and bottom punches are movable. When the bottom punch is in the low position a cavity is formed in the die and this cavity is filled with free flowing powder. In dry pressing the powder mixture will contain between 0 and 5 wt% of a binder. (So, dry does not imply that there is no binder.) Once the cavity has been filled, the powder is struck off level with the top of the die. The top punch descends and compresses the powder either to a predetermined volume or to a set pressure. During pressing the powder particles must flow between the closing punches so that the space between them is uniformly filled. A particle size distribution of between 20 and 200 μm is often preferred for dry pressing: a high volume fraction of small particles causes problems with particle flow and also results in sticking of the punches. The pressures used in dry pressing may be as high as 300 MPa, depending upon material and press type, to maximize the density of the compact. After pressing, both punches move upward until the bottom punch is level with the top of the die and the top punch is clear of the powder-feeding mechanism. The compact is then ejected, the bottom punch is lowered, and the cycle is repeated.

Because the dry-pressing process is so simple and involves low capital equipment costs it is the most widely used high-volume forming process for ceramics. Production rates depend on the size and shape of the part and on the type of press used. For large components such as refractories or complex parts such as grinding wheels the production rates are 1–15 parts per minute. During a tour of the Wedgwood factory, you will see dinner plates being dry pressed in a continuous process. Simpler or smaller

shapes such as seal rings and nozzles can be produced at rates up to several hundred per minute. Small flat parts such as insulators, chip carriers, or cutting tools can be produced at rates up to several thousand per minute.

23.5 HOT PRESSING

Pressing can also be performed at high temperatures; this process is known as hot pressing. The die assembly used for hot pressing is very similar to that described in Section 23.4 for dry pressing. The main difference is that in hot pressing the die assembly is contained within a high-temperature furnace as shown in Figure 23.2. During hot pressing the ceramic powders may sinter together to form a high-density component.

We can summarize the advantages of this process.

- The powder does not have to be of the highest quality.
- Large pores that are caused by nonuniform mixing are easily removed.
- We can densify at temperatures lower (typically half the melting temperature of the material) than those needed for conventional pressureless sintering.
- Extensive grain growth or secondary recrystallization does not occur when we keep the temperature low during densification.
- We can densify covalently bonded materials such as B₄C, SiC, and Si₃N₄ without additives.

The principal disadvantage is also important.

- Dies for use at high temperatures are expensive and do not generally last long.




FIGURE 23.2 Schematic showing the essential elements of a hot press.

TABLE 23.2 Hot Pressed Products

Product	Types of material
Optical windows	IR: MgF ₂ , ZnS, ZnSe; visible: Y ₂ O ₃ , MgAl ₂ O ₄
Ceramic armor	B ₄ C, TiB ₂ , SiC, Al ₂ O ₃
Cutting tools	Al ₂ O ₃ particle-reinforced TiC, Si ₃ N ₄ , Si ₃ N ₄ -AlN-Al ₂ O ₃
Tooling (molds and dies)	Al ₂ O ₃ -SiC _w composites, SiC, Al ₂ O ₃
Sputtering targets	Cr-SiO, TiN, Si ₃ N ₄ , B ₄ C, Al ₂ O ₃
Heat engine components	Si ₃ N ₄ , SiC
Ceramic bearings	Si ₃ N ₄
Microwave absorbers	MgO-SiC particulate composites, BeO-SiC, Al ₂ O ₃ -SiC
Varistors	ZnO
Electrooptic materials	PLZT
Titanates	BaTiO ₃ , CaTiO ₃
Microelectronic packages	Cofired W-metallized AlN
Resistors	Si ₃ N ₄ matrix with particulates of TiB ₂ , TiC, TiN, or SiC as the dispersed conducting phase

Most metals are of little use as die materials above 1000°C because they become ductile, and the die bulges. Special alloys, mostly based on Mo, can be used up to 1000°C at pressures of about 80 MPa. Ceramics such as Al₂O₃, SiC, and Si₃N₄ can be used up to about 1400°C at similar pressures. Graphite is the most widely used die material and can be used at temperatures up to 2200°C and pressures between 10 and 30 MPa. The difficulty is that a graphite die will tend to produce a very reducing environment. (You can make an Al₂O₃ sample vanish using a graphite die!)

However, graphite does have many properties that make it suitable for a die.

- It is easy to machine (but the dust is toxic if inhaled—like coal dust).
- It is inexpensive.
- Its strength increases with increasing temperature.
- It has good creep resistance.
- It has excellent thermal conductivity.
- It has a relatively low coefficient of thermal expansion.

Hot pressing, like dry pressing, is limited to simple solid shapes, such as flat plates, blocks, and cylinders. More complex or large shapes are difficult and often impossible to produce by hot pressing. Hot pressing is widely used in the research laboratory for processing very dense, high-purity ceramic components. Although it is extensively used in university and government laboratories, the technique is limited as a production tool because of its high cost and low productivity. For any mass-produced ceramic product there would be considerable commercial pressure for a company to find a less expensive alternative. However, some commercial hot-pressed ceramic products are available. These products require a

small grain size, a high density (low porosity), or low impurity levels. Examples of such products are given in Table 23.2.

Isostatic pressing involves the application of hydrostatic pressure to a powder in a flexible container. The advantage of applying pressure in all directions is that there is more uniform compaction of the powder and more complex shapes can be produced than with uniaxial pressing. Isostatic pressing can be performed either with or without applied heat.

23.6 COLD ISOSTATIC PRESSING

There are many variations on using the cold isostatic press (CIP); here we just emphasize some basic themes. Figure 23.3 illustrates the so-called wet-bag CIP process. Powder is weighed into a rubber bag and a metal mandrel is inserted that makes a seal with the mouth of the rubber bag. The sealed bag is placed inside a high-pressure chamber that is filled with a fluid (normally a soluble oil/water mixture) and is hydrostatically pressed. The pressures used can vary from about 20 MPa up to 1 GPa depending upon the press and the application. For production units the pressure is usually ≤400 MPa. Once pressing is complete, the pressure is released slowly, the mold is removed from the pressure chamber, and the pressed component is removed from the mold.

The advantages of the wet-bag process are

- Wide range of shapes and sizes can be produced
- Uniform density of the pressed product
- Low tooling costs

The disadvantages are

- Poor shape and dimensional control (particularly for complex shapes)




FIGURE 23.3 Schematic of a wet-bag isostatic pressing system.




FIGURE 23.4 Schematic of a die for dry-bag isostatic pressing of a spark plug insulator.

- Products often require green machining (described in Section 23.14) after pressing
- Long cycle times (typically between 5 and 60 minutes) give low production rates

A small wet-bag isostatic press, used to produce laboratory samples and low-volume production parts, might have an internal diameter of 150 mm and a depth of 460 mm. Large wet-bag presses may have cavity diameters >1.8 m and lengths up to 3.7 m. The wet-bag CIP process can be automated.

A schematic diagram of a mold for the dry-bag CIP is shown in Figure 23.4. The main distinction of the dry-bag process is that the rubber mold is now an integral part of the press. The high-pressure fluid is applied through channels in the mold. After pressing, the pressed part is removed without disturbing the mold. Hence, the dry-bag press can be readily automated. Fully automated units are widely available and have been operating in the high-volume production of ceramic parts for over 20 years.




FIGURE 23.5 Making spark plugs. Hydrostatic pressure is applied by pumping oil around the rubber container, which is part of the press and thus easily removed.




FIGURE 23.6 Schematic of a hot isostatic pressing apparatus.

Production rates of up to 1 part per second are being achieved industrially.

The dry-bag CIP has been used for many years to press spark plug insulators. The steps in this process are shown in Figure 23.5. Notice the insertion of the inner pin in the mold. The world's largest producers of spark plugs produced by this method are Champion and AC Spark Plug.

23.7 HOT ISOSTATIC PRESSING

The hot isostatic press (HIP) uses the simultaneous application of heat and pressure. We refer to this process as HIPing and the product as being HIPed (but you will see variations on these abbreviations). A furnace is constructed within a high-pressure vessel and the objects to be pressed are placed inside. Figure 23.6 shows a typical HIP arrangement. Temperatures can be up to 2000°C and pressures are typically in the range of 30–100 MPa. A gas

is used as the pressure medium, unlike the CIP in which a liquid is often used. Argon is the most common gas that is used for HIPing, but oxidizing and reactive gases can also be used. Note that the high-pressure vessel is not inside the furnace.

There are two variants of HIPing:

- Encapsulated: using a deformable container
- Not encapsulated: it is shaped and sintered first, then HIPed

In the original HIPing method the ceramic powder was filled into a deformable metal can and then subjected to heat and pressure. This method was subsequently modified for small particle sized powders. The powder compact was preformed to the desired shape by a process such as dry pressing or injection molding. The green compact was then encapsulated in a glass envelope that could be removed from the product after HIPing as shown in Figure 23.7.

The second variant does not involve encapsulation. The ceramic powder is first compacted using another shaping method such as dry pressing or injection molding. It is then sintered at relatively high temperatures in a furnace to close all the surface pores, which prevents the entry of the gas during subsequent HIPing. The steps in this process, which is sometimes referred to as sinter-plus-HIP, are shown in Figure 23.8.

Now HIPing is used for a wide variety of ceramic (and metallic) components, such as alumina-based tool bits and the silicon nitride nozzles used in flue-gas desulfurization plants by the utility industry. The advantages of the HIPing process are becoming more important as interest in structural ceramics such as Si_3N_4 grows.

Nonoxide ceramics can be HIPed to full density while keeping the grain size small and not using additives. Very high densities combined with small grain sizes (because of the relatively low temperatures) lead to products with

HIP AND HIPING

Used initially for fabricating the cladding for nuclear fuel elements. It was called “gas-pressure bonding.”

We use the acronym HIP to identify the press and HIPing to identify the action. You will also see HIP used to mean HIPing and you will see HIPing spelled HIPping! We then say a sample has been HIPed rather than HIPped. Only nano is HYPed.

special mechanical properties. HIPing has also been applied to the formation of piezoelectric ceramics such as BaTiO_3 , SrTiO_3 , and lead zirconate titanate (PZT) for use in acoustic wave filters and oscillators.

Uses: produces dense materials without growing the grains

Disadvantage: cost

23.8 SLIP CASTING

The slip is poured into a mold (usually plaster of Paris: $2\text{CaSO}_4 \cdot \text{H}_2\text{O}$) that has been made by casting round a model of the required shape, which was itself suitably enlarged to allow for the shrinkage of the cast ceramic on drying and sintering. The fineness of the powder (in the slip) and the consequent high surface area ensure that electrostatic forces dominate gravity so that settling does not occur. The electrochemistry of the slip is quite complex: Na silicate (or soda ash) is added to the slip to deflocculate the particles. The water passes, via capillary action, into the porous plaster leaving a layer of the solid on the wall of the mold. (We consider this model in Section 25.7.) Once a sufficient thickness has been cast, the surplus slip is poured out and the mold and cast are allowed to dry. These steps are shown in Figure 23.9. This variant of slip casting, which is the most widely used, is also called drain casting. A very effective technique used by some potters is to produce a multilayer slip, parts of which are removed before firing.

Slip casting is a low cost way to produce complex shapes and in the traditional pottery industry it is the accepted method for the production of teapots, jugs, and figurines, although handmade items will likely be hand-thrown. Large articles, such as wash-hand basins and other whitewares, are also mass produced by slip casting. (Whitewares are not necessarily white.) One of the telltale




FIGURE 23.7 Individual steps of cold preforming, canning, HIPing, and stripping in the standard HIPing process.




FIGURE 23.8 Individual steps of cold forming, sintering, and HIPing in the sinter plus HIPing process.




FIGURE 23.9 Schematic illustrating the drain-casting process. (a) Fill the mold with slip; the mold extracts liquid, forming a compact along the mold walls; (b) after excess slip is drained and after partially dried, green ceramic is removed.

signs of a ceramic product made by slip casting is that it is hollow. Another variant of the slip casting process is solid casting. In solid casting, slip is continually added until a solid cast is made. These items will not be hollow—relatively, they will be heavier.

Slip casting is also used in the fabrication of some technical and structural ceramics. It is the standard method used to make alumina crucibles and has been successfully used to make complex structural ceramic components such as gas-turbine rotors. The technique of doctor-blading, which we discuss in Chapter 27, is just another method of shaping the slip—ensuring that the slip is spread as a uniform layer.

23.9 EXTRUSION

Extrusion involves forcing a deformable mass through a die orifice (like toothpaste from a tube). The process is widely used to produce ceramic components having a




FIGURE 23.10 Extrusion of (a) a rod and (b) a tube.

uniform cross section and a large length-to-diameter ratio such as ceramic tubes and rods as illustrated in Figure 23.10. Clay with a suitable rheology for the extrusion process (essentially a paste) can be made by controlling the amount of water. Clay-free starting materials, such as Al_2O_3 , are mixed with a viscous liquid such as polyvinyl alcohol or methylcellulose and water to produce a plastically deformable mass. Table 23.3 lists the compositions of some extrusion bodies. Extrusion of polymers has been used since the 1860s; it was originally used to process natural rubber. An extrusion press like those shown in Figure 23.11 is standard equipment in the potter's barn.

Extrusion is also used to produce the alumina shells for sodium vapor lamps and the honeycomb-shaped catalyst supports for automotive emission-control devices (see Chapter 37). The catalyst supports are designed to give a high surface area and can consist of hundreds of open cells per square centimeter with wall thicknesses $<100\mu\text{m}$. To produce these shapes, cordierite ceramic powder is mixed with a hydraulic-setting polyurethane resin. The mix is extruded into a water bath at a rate that matches the rate of cure of the polyurethane (about 2 mm/s). It is then fired to produce the final ceramic.

TABLE 23.3 Examples of Compositions of Extruded Bodies (Composition in vol%)

Refractory alumina		High alumina		Electrical porcelain	
Alumina ($<20\mu\text{m}$)	50	Alumina ($<20\mu\text{m}$)	46	Quartz ($<44\mu\text{m}$)	16
Hydroxyethyl cellulose	6	Ball clay	4	Feldspar ($<44\mu\text{m}$)	16
Water	44	Methylcellulose	2	Kaolin	16
AlCl_3 (pH > 8.5)	<1	Water	48	Ball clay	16
		MgCl_2	<1	Water	36
				CaCl_2	<1



(A)



(B)

FIGURE 23.11 Extruding clay. Manual and electric extruders.

23.10 INJECTION MOLDING

Injection molding is another technique that is widely used in shaping thermoplastic polymers. A thermoplastic polymer is one that softens when heated and hardens when cooled. Such processes are totally reversible and may be




FIGURE 23.12 Cross-sectional side view of a screw-type machine.

repeated. Injection molding can be applied to shaping and forming ceramic components if the ceramic powder is added to a thermoplastic polymer. When forming ceramics by injection molding, the polymer is usually referred to as the binder (but we could instead have called the material a ceramic-loaded polymer). The ceramic powder is added to the binder and is usually mixed with several other organic materials to provide a mass that has the desired rheological properties. Table 23.4 shows the additives that have been used to form SiC shapes by injection molding. The organic part of the mix accounts for about 40 vol%.

The plastic mass is first heated, at which point the thermoplastic polymer becomes soft and is then forced into a mold cavity as shown in Figure 23.12. The heated mixture is very fluid and is not self-supporting (this is different from the situation encountered in extrusion). The mixture is allowed to cool in the mold during which time the thermoplastic polymer hardens. Because of the large volume fraction of organic material used in the mixture, there is a high degree of shrinkage of injection-molded components during sintering. Shrinkage of 15–20% is typical, so precise control of component dimensions is difficult. However, complex shapes are retained with very little distortion during sintering since the densities, although low, are uniform.

TABLE 23.4 Additives for Injection Molding of SiC

Function	Example	Quantity (wt%)	Volatilization temperature
Thermoplastic resin	Ethyl cellulose	9–17	200–400°C
	Polyethylene		
	Polyethylene glycol		
Wax or high-temperature volatilizing oil	Paraffin	2–3.5	150–190°C
	Mineral oils		
	Vegetable oils		
Low-temperature volatilizing hydrocarbon or oil	Animal oils	4.5–8.5	50–150°C
	Vegetable oils		
	Mineral oils		
Lubricant or mold release	Fatty acids	1–3	
	Fatty alcohols		
	Fatty esters		
Thermosetting resin	Epoxy		Gives carbon 450–1000°C
	Polyphenylene		
	Phenol formaldehyde		

Injection molding is used to fabricate ceramic components with complex shapes; because cycle times can be rapid, injection molding can be a high-volume process. The major limitation is that the initial tooling costs of the mold can be quite high. The mold to fabricate an individual turbine blade can be >\$10,000 and a mold for a turbine rotor may be >\$100,000, but such molds are reusable since they are never subjected to high temperatures.

23.11 RAPID PROTOTYPING

Rapid prototyping (RP) or solid freeform fabrication (SFF) is a relatively recent approach to forming ceramic components. There are various forms of RP techniques, but they are based on a common principle: a computer directly controls the shaping process by accessing computer-aided design (CAD) files. We can thus use RP to form a 3D component without the use of a die or a mold. RP techniques are used commercially for fabrication of parts from polymers for design verification and form-and-fit applications; these techniques have more recently been applied to forming parts out of ceramics.

In this section we will look at just two of the several RP methods

Stereolithography (SLA)

Fused deposition modeling (FDM)

Both these methods have been successfully used to form ceramic components. The SLA process is illustrated in Figure 23.13. In SLA the component is formed from an epoxy resin. As the z-stage elevator is lowered, an ultraviolet (UV) laser beam whose position is controlled by a computer cures successive layers of the uncured resin. In this way a 3D component is made one layer at a time. It can take many hours to build a large complex object. But this is still rapid compared to the time taken to form a component by, e.g., injection molding, where fabrication of the tools can take a considerable amount of time. To form ceramic components by SLA the polymer must be




FIGURE 23.13 Schematic representation of the SLA SFF process.




FIGURE 23.14 Schematic representation of the fused deposition (FD) SFF process.

loaded with ceramic powders. Si_3N_4 , SiO_2 , and Al_2O_3 powders have all been used for SLA.

In FDM the source material is a thermoplastic polymer filament that is heated and extruded to form the product as shown in Figure 23.14. The product is formed in a layer-by-layer manner similar to building up layers of icing on a cake. The computer controls the x - y position of the filament and the deposition rate. The filament can be loaded with up to 60 vol% ceramic powders; once the part is completed the binder is removed and the part is sintered. Most of the work in the RP of ceramic parts by FDM has involved Si_3N_4 . The feasibility of making components out of Al_2O_3 , SiO_2 , and PZT has also been demonstrated. The abbreviation FDC (fused deposition of ceramics) is used to identify this special application of FDM.

23.12 GREEN MACHINING

To obtain the desired shape of a ceramic product it is often necessary to machine it. Machining can be performed either before or after the product has been sintered. If the machining is done before sintering, while the component is still in the green state, the process is called green machining. The advantages of green machining compared to machining the sintered product are that there is a considerable reduction (10 \times) in machining time and a 20 \times reduction in cost because of less tool wear and the possibility of using cheaper tools. Table 23.5 compares the use

TABLE 23.5 Comparison of Cutting Speed versus Tool Life

Tool material	Cutting speed (m/min)	Work-piece material removed (cm^3)	Relative cost factor
Cubic BN	30	8.2	\times
Ti-coated carbide	30	13.1	\times
Co-coated WC	30	19.7	\times
Diamond	90	8500	10 \times

of different tool materials in the green machining of an Si compact before nitriding it to form Si_3N_4 .

In the processing of spark plug insulators the final processing step prior to firing involves green machining as shown earlier in Figure 23.5.

23.13 BINDER BURNOUT

In pottery, the binder burnout is the removal of water from the shaped clay. The rest of the firing process causes structure changes and transformations in the silicate itself. Forming methods for engineering ceramics, like injection molding, produce green bodies that can contain 30–50 vol% of organic binder. We generally want to remove this binder without cracking or distorting the ceramic compact. Binder burnout is one of the most likely stages to form defects in the processing of a ceramic: macroscopic defects, such as cracks and blisters, can be introduced at this stage, and these will affect the mechanical strength and other properties. An additional complication is that the binder system used in fabricating many commercial ceramic parts often consists of several components. These components have different boiling points and decomposition temperatures.

The components with low boiling points (e.g., waxes) may be removed by evaporation at fairly low temperatures.

Oxidation or decomposition at higher temperatures removes high-molecular-weight components.

For oxide ceramics, the binder can be oxidized to form H_2O , CO , and CO_2 when the green compact is heated in air. Binder burnout in air generally presents no problem. However, there are some situations in which binder burnout in air can be a problem. An example is the use of poly(vinyl butyral) with Al_2O_3 where carbon residues can be as high as thousands of parts per minute even after burnout in air at 700°C for 24 hours. Nonoxide ceramics generally cannot be heated in oxidizing environments and binder burnout in inert or reducing atmospheres is more difficult. Pyrolysis of many binders in these environments is not well understood and most binders leave some carbonaceous residue that could be detrimental to the subsequent sintering stage.

The process of binder removal is kept slow to reduce the possibility of macrodefects being produced. Figure 23.15 shows a plot of a binder removal cycle. In this plot a pressurized gas, called a *sweep gas*, has been passed over the part to help sweep away the vapor. The cycle time also depends on the size of the part. Thin sections take much shorter times than thick sections. The *debinding* time is proportional to the square of the section thickness of the compact—the familiar parabolic kinetics seen in our discussion of reactions in Chapter 25.




FIGURE 23.15 Pressure-induced binder removal cycle.

Binder burnout continues to be an active area of ceramics research with one of the main thrusts being in developing models of binder decomposition and diffusion.

23.14 FINAL MACHINING

Ideally the shaping and forming processes that are employed would produce the ceramic component in the desired shape with the specified dimensional tolerances and with an acceptable surface finish. However, in many cases this is not the situation and some final machining (after firing/sintering) of the ceramic is necessary. Generally final machining is required to

- Meet dimensional tolerances
- Improve the surface finish
- Remove surface flaws

Machining fired ceramics can be expensive and can represent a significant fraction of the total fabrication costs. Ceramic materials are difficult to machine because they are hard and brittle. The tooling costs are high because diamond tools are likely to be required or if conventional tools are used the tool life is very short. Also the time required to machine ceramics is long because if high tensile loads are applied to the ceramic part it might fracture.

Mechanical approaches to machining ceramics include the following:

- *Grinding* uses tools in which abrasive particles are embedded in a softer matrix such as glass, rubber, or polymer resin, or even a metal (as for WC in Co).
- *Lapping* uses loose abrasive particles placed on a soft cloth.
- *Sandblasting* uses abrasive particles accelerated by compressed air and directed through a nozzle at high velocity.




FIGURE 23.16 Schematic of the abrasive waterjet cutting process.

- *Water-jet machining* uses a high-pressure (~400 MPa pumping pressure) water jet to transport the abrasive particles to the ceramic surface.

The water-jet method is gaining popularity as a high-speed method for machining hard ceramics. Figure 23.16 shows the basic components of an abrasive water-jet cutter. Cutting rates depend on the material being cut and can vary from 130 mm/min for glass to 5 mm/min for a dense hard ceramic such as TiB₂. In a water-jet, the water is pressurized to ~380 MPa and is forced through a sapphire orifice at a velocity of up to about 750 m/s; in the abrasive jet, the speeds may be a little lower, but garnet powder is pulled into the water stream and acts as the abrasive to cut through, e.g., 25 mm of Ti or steel. It can also cut through ceramics and glass. Of course, dentists use the same technique when working on our teeth. The Grand Canyon was formed on a larger scale by essentially the same process. Masons use sandblasting to clean the surfaces of old stone buildings.

23.15 MAKING POROUS CERAMICS

In many traditional applications for ceramics, particularly in structural and electrical applications, the sintered ceramic component is required to have minimum porosity. However, in a growing number of applications, for example, in ceramic humidity and gas sensors, porosity is not just desirable, it is required. Several different methods can be used to produce porous structures.

- Use large particles with a very small size distribution to avoid dense packing.
- Underfire a green compact to leave a large amount of fine pores.
- Add organic particles (diameter >20 μm) to the powder mixture; when these burn out they will leave behind porosity. We use a controlled version of this technique elsewhere to produce mesoporous photonic materials.
- Use a binder system that contains a foaming agent and produces a large amount of gas bubbles in the mixture.
- Impregnate a foam that has a continuous porosity and then burn it out.
- Use a glass composition that phase separates and then leaches out (e.g., using an acid) one of the phases to produce porous glasses.

Mesoporous materials, which have quite a uniform distribution and a very high density of pores, were discussed in Chapter 15.

23.16 SHAPING POTTERY

We stated at the beginning that this chapter is the pottery chapter. We will now summarize areas in which many of the techniques described above have been used, in some cases for millennia, in pottery; then we can do the same for glass. Classical porcelain can be as thin as a sheet of paper (<0.2 mm). Bone china, so called because even today it is made by adding ~50% bone ash to a conventional hard-porcelain clay mixture, can be so thin that it is translucent. This ingredient is so critical that the UK imports bone ash from Argentina.

Paper clay is a relatively new material for the potter being a mixture of clay and paper in approximately equal amounts by volume. The paper (cellulose fiber) gives added strength to the green body so it can even be made into a sheet that can then be cut and shaped before firing. The firing burns out the organics and leaves a ceramic body that is lighter than usual. Figure 23.17 shows a sheet of paper clay being lifted off the plaster “substrate” (see also Section 25.7). As you might guess, there are many variations on this process, which of course are related to the ancient use of straw in making house bricks.

Throwing a pot, as shown in Figure 23.18, is the process of producing hollow clay objects on a revolving pottery wheel. Potters may use their hands as shown here, or other tools—the step to industry is then a small one.

Coiling, pinching, and slabbing are used to form large pottery objects. Their common feature is that the total thickness of the ceramic piece is kept constant so that the drying and firing process will be even. Wedging is not a shaping process, although the end result is a slab of clay. Rather, it is the process used to remove porosity from clay before it is used to make a pot. This is now carried out mechanically in a pug mill. If you pinch the clay or carve



FIGURE 23.17 Removing paper clay from the substrate.



FIGURE 23.18 Throwing a pot.

it, you can combine different colored clays and shape and fire them to produce the neriage (marbled) style of the potters version of millefiore.

23.17 SHAPING GLASS

Glass can be shaped by many different processes.

Casting or molding has produced, for example, the 20-inch-thick Palomar telescope mirror and the submilli-

meter-thick molded-glass aspheric lenses that are used in everything from laser printers to optical disc storage devices and optical communications systems.

Pressing needs a mold that will be gray cast iron (to 1000°C), stainless steel (can be used for borosilicates at 1185°C and glass ceramics at 1480°C), or even bronze. Usually, though, the mold is cooled. The process uses a viscosity of ~4 kP and has been applied to objects weighing from 5 g to 15 kg. The finished object can be fire-polished. This process, shown in Figure 23.19, is quite




FIGURE 23.19 Automated pressing glass.

similar to the HIPing technique shown in Figure 23.2 and predates it, of course.

Sagging or slumping is a simple method whereby the glass is heated so that it “slumps” into the mold. The technique can also be used for clay; effectively it is pressing, with gravity providing half the press.

Glass blowing was clearly in use in the first century BCE. The temperature is critical since it determines the working range. There will be other factors such as the air pressure, the role of gravity, and the centrifugal force produced by the blower. The craftsman will produce free-blown objects or can blow the glass inside a mold. When a ribbon or hub machine is used, the glass is invariably blown into a mold.

Drawing is used for glass tubes and sheets. For tubes the variations include Danner (e.g., tubes for fluorescent lights), Vello (large diameter tubes), downdrawn tubes (used for vacuum tubes or uses a vacuum), and updrawn tubes (for glass thermometers). Sheets are drawn in the same way: using a slot orifice, with an overflow pipe, using updraw or floating.

Spinning is used for fibers and is very reminiscent of the beginnings of industry (the spinning jenny).

Rolling is an old technique that is still in use. It is similar to slabbing in pottery.

The lost wax process of forming glass shapes has been used since the fifth century CE. Originally, the molten glass was poured into an outer mold made of beeswax, which could easily be removed.

Inlays in glass, such as sandwiched-gold glass, was made perhaps as early as ~250 BCE. Gold leaf is pressed between two layers of glass.

Final machining using Vycor (the “cor” is from Corning), Macor, or similar specially treated glasses. (Vycor contains “built-in” pores; Macor contains small grains of mica.)

Core forming was one of the earliest methods used to shape glass (see Figure 21.3). A shape was fashioned in clay and the glass was then trailed around the core until it completely covered it. It could be heated further so that the coils fused together. When cool, the clay core would be removed leaving a stand-alone glass vessel.

CHAPTER SUMMARY

In this chapter we described the methods used to shape and form ceramic components. There are a number of possible choices and the best one depends on the types of shapes being produced, the cost of the component, and the number of units being made. For predominantly covalently bonded ceramics it is necessary to use shaping techniques that involve the application of pressure and heat if the objective is to obtain a high-purity material. Because ceramics cannot be softened in the same way as polymers and metals it is often necessary to form a plastic mixture of the ceramic prior to shaping. These methods may leave a large amount of organic residue that must be removed during sintering. Binder removal is tricky because it can lead to the formation of voids and cracks in the ceramic component. Machining of ceramics is often performed when they are in the green state—before sintering. This is because the presintered component is much softer and tooling costs are significantly reduced. A relatively recent approach to forming ceramic components is rapid prototyping. The advantage of this technique is that 3D parts can be made without using a die or a mold. The technique has been well established for producing parts made of polymeric materials and is now being extensively investigated for forming ceramic components.

PEOPLE IN HISOTRY

Brown, Robert, the Scottish botanist (1773–1858), among other activities studied the movement of particles (pollen and inorganic) in water and thus recognized Brownian motion.

Champion, Albert founded two companies—Champion and AC Spark Plug. In the 1990s, between them they produced over one-half of the world’s spark plugs. McDougal (1949) gives a review of these two companies.

Hamada, Shoji (1892–1978) was born in Tokyo. His home and his pottery are in Mashiko, which is a ceramics town just a short drive north of Tsukuba.

Kawai, Kanjiro (1890–1966) lived in Kyoto in a house that is now another wonderful museum.

Leach, Bernard Howell (1887–1979) is probably the best-known British potter. He was born in Hong Kong and worked in Japan (with Shoji Hamada) and at St. Ives in England.

Spode, Josiah (1733–1797) founded his pottery in 1770 at Stoke. He developed the formula for bone china that is still used.

Tomimoto, Kenkichi (1795–1835) was born and raised in Japan and helped make style part of everyday Japanese pottery.

Wedgwood, Josiah (1730–1792) was born in Burslem, Staffordshire. He joined the firm of Thomas Wheildon at Fenton, who gave him the freedom to experiment, and founded a factory in Etruria with his business

partner Thomas Bentley. He was elected a Fellow of the Royal Society for inventing the pyrometer: he used the fact that porcelain shrinks in the furnace to measure the temperature of the furnace. His daughter, Susannah, had a son, Charles Darwin.

Yanagi, Soetsu (1889–1961) created the mingei (folk art) movement in Japan in the 1920s; this movement has influenced much of Japan's stunning pottery.

GENERAL REFERENCES

For information on modeling binder removal see the papers by Barone and Ulicny (1990), Stangle and Aksay (1990), Evans *et al.* (1991), and Matar *et al.* (1993).

Birks, T. (1998), *The Complete Potter's Companion*, Bulfinch Press, Boston. Photos of techniques are especially clear and instructive.

Engineered Materials Handbook, Volume 4, *Ceramics and Glasses*, ASM International. Section 3 covers, in considerable detail, many aspects of shaping and forming as practiced in industry.

Leach, B. (1944) *A Potter's Book*, Faber & Faber Ltd., London.

Onoda, G.Y. and Hench, L.L. (1978) *Ceramic Processing Before Firing*, Wiley-Interscience, New York.

Peterson, S. (2003) *The Craft and Art of Clay*, 4th edition, The Overlook Press, Woodstock, NY. Much more than shaping; glazes, kilns, design, history.

Rahaman, M.N. (1995) *Ceramic Processing and Sintering*, Marcel Dekker, New York. Less well known than Reed but very useful.

Reed, J.S. (1988) *Introduction to the Principles of Ceramic Processing*, John Wiley, New York. A classic text on processing.

Richerson, D.W. (2006) *Modern Ceramic Engineering*, 3rd. edition, CRC Press, Boca Raton, FL. Chapter 13 describes the important shape-forming processes.

Solid Freeform Fabrication Symposium Proceedings (held annually, University of Texas, Austin). The formation of ceramic components by RP or SFF is a developing field. These proceedings give current information.

SPECIFIC REFERENCES

Barone, M.R. and Ulicny, J.C. (1990) "Liquid-phase transport during removal of organic vehicle in injection moulded ceramics," *J. Am. Ceram. Soc.* **73**, 3323.

Evans, J.R.G., Edirisinghe, M.J., Wright, J.K., and Crank, J. (1991) "On the removal of organic vehicle from moulded ceramic bodies," *Proc. R. Soc. (London)* **A432**, 321.

German, R.M. (1987) "Theory of thermal debinding," *Int. J. Powder Met.* **23**, 237. Classic article on this topic.

Gault, R. (2005) *Paper Clay (Ceramics Handbook)*, 2nd edition, A&C Black, London.

Mater, S.A., Edirisinghe, M.J., Evans, J.R.G., and Twizell, E.H. (1993) "The effect of porosity development on the removal of organic vehicle from ceramic or metal mouldings," *J. Mater. Res.* **8**, 617.

McDougal, T.G. (1949) "History of AC spark plug division, General Motors Corporation," *Am. Ceram. Soc. Bull.* **28**, 445.

Stangle, G.C. and Aksay, I.A. (1990) "Simultaneous momentum, heat and mass transfer with chemical reaction in a disordered porous medium: Application to binder removal from a ceramic green body," *Chem. Eng. Sci.* **45**, 1719.

WWW

www.stratasys.com/NA/index.html
A commercial supplier of FDM equipment and software.

www.optima-prec.com
For molded glass lenses

www.raku-yaki.or.jp
The Raku Museum

www.ceramicsmuseum.alfred.edu
The site for Alfred's museum.

www.omax.com
For information on abrasive waterjets.

www.pottery-making.org
Pottery Making Illustrated.

EXERCISES

- 23.1 Explain briefly why melting and solidification can be used for shaping glasses (as well as many metals and polymers) but in general not for forming crystalline ceramics.
- 23.2 Briefly describe the differences between hot pressing and cold pressing.

- 23.3 Explain why hot pressing is often used when ceramics with a small grain size are required. For what applications must grain growth be minimized?
- 23.4 Why are graphite dies widely used for hot pressing? Under what conditions would the use of graphite not be appropriate?
- 23.5 Which method would you choose to form each of the following shapes; briefly justify your choice. (a) A cylinder; (b) a tube; (c) a cube; (d) a teapot; (e) a rotor blade; (f) a spark plug insulator; (g) an insulator for a power cable.
- 23.6 Why is it necessary to use an organic binder when forming a ceramic component by extrusion? What are the main requirements for the binder?
- 23.7 Why is it difficult to use injection molding for near net shape manufacturing?
- 23.8 Briefly explain why it is better to machine in a ceramic component when it is in its green state rather than when it has been fired.
- 23.9 Keramica is a new company that wants to manufacture alumina furnace tubes and they hire you as a consultant. You are asked to propose a process for the fabrication of such tubes. Give a general description of the process you would propose. Explain the roles of the different steps involved.
- 23.10 Porcelain figurines are manufactured worldwide in large quantities. In most cases, many figures are made with an identical shape. As you know, such figures are often hollow. Explain the process used to form such figures economically.